

BRASTER S.A.

BRASTER MEDICAL CENTER
 nr w rej. Podmiotów leczniczych 000000179072
 ul. Sokołowska 9, 01-142 Warszawa lok. U-02
 Gabinet termograficzny
 Tel. (22) 295 03 50

**Thermography test interpretation dated 05.11.2021
 ordered on 05.11.2021**

ID 4711		
Examination ID Miss.Thilagakani 1421823	Date of birth 15.11.1992	Age 28

Examination details

Clinic: 692, Dr Umamaheshwari-CLINIC; Examiner: 4879, Dr Umamaheshwari; Device number: BRA-007191, Day of menstrual cycle: 7. Examination was performed using matrix number 3.

Thermographic examination interpretation:


The interpretation of the examination did not detect any thermal irregularities. Further breast control as prescribed by your physician is recommended.

Details of Braster® AI analysis

	Value:	Norm:
Thermal asymmetry parameter:	0,00*	from -2 to 2
Structure asymmetry parameter:	-0,93*	from -2 to 2
Main thermal structure area ratio:	3,04*	from -4 to 4
Main difference ratio of surface thermal structures areas:	25 560,50*	from -20,000 to 20,000

* Coefficients were considered to be insignificant on the basis of vision analysis

Original images (matrix no. 3)



Braster Pro is part of a multifaceted diagnostic process and is not intended for independent diagnosis.

This document is a translation of a document created in Polish. In the case of differences in the content of the document in two language versions, the Polish version of the document applies.